



INSIGHT GLASS™



A True Indication of Tank Integrity

When a diaphragm or bladder expansion tank fails, system water enters the gas space, causing the tank to become waterlogged and ineffective, often leading to unnoticed pressure spikes and costly system damage. Common color-change failure indicators can be unreliable due to false readings from ambient humidity.

Introducing the InSight Glass™, **NOW standard** on all Amtrol commercial diaphragm and bladder HVAC and potable water expansion tanks, providing a clear and dependable visual indication of tank integrity.



- 1-1/4" coupling size.
- Buoyant ball will float when water enters the sight glass provides clear indication without false positives.
- Tilted angle up allows visibility into the glass while standing allows the glass to remain low for early detection.
- Multiple through holes into the vessel inside the coupling allow a swirling motion and earlier detection of failures.



Mounted at a 12° upward angle, the InSight Glass uses a buoyant indicator ball that floats and visibly agitates when water enters the gas space, allowing for early, positive, and unmistakable identification of tank failure. **A True Indication of Tank Integrity.**

3
Years



1400 Division Road, West Warwick, RI 02893 USA
T: 800.426.8765 www.amtrol.com

